

**Table 3**  
**Radon Analytical Results Summary**  
**Canadian Radium And Uranium Site**  
**Kisco Avenue, Mount Kisco, New York**

RST 3 Sample No.	Canister Serial No.	Results	Std. Error	Start		Stop		Sample Type	Floor	Location
		(pCi/L)	(pCi/L)	Date	Time	Date	Time			
Property C001 - Milepost 136, 103 Kisco Avenue										
C001-AA001-01	2432014	0.4	+/- 0.2	8/4/2015	8:30	8/7/2015	8:51	Field Sample	Ground	MTA substation B36, 9' East, 5' South from NW corner on PEI stand
C001-AA002-01	2430438	0.4	+/- 0.2	8/4/2015	8:33	8/7/2015	8:53	Field Sample	Ground	MTA substation B36, 10.2' East, 31.5' South from NW corner on PEI stand
C001-AA002-02	2430473	0.3	+/- 0.1	8/4/2015	8:34	8/7/2015	8:53	Field Duplicate	Ground	MTA substation B36, 10.7' East, 31.5' South from NW corner on PEI stand
C001-AA003-01	2430461	0.4	+/- 0.1	8/4/2015	8:37	8/7/2015	8:55	Field Sample	Ground	MTA substation B36, 32.2' North, 2.5' West from SE corner on PEI stand
C001-AA004-01	2430552	0.4	+/- 0.1	8/4/2015	8:40	8/7/2015	8:57	Field Sample	Ground	MTA substation B36, 3' North, 7.5' West from SE corner on PEI stand
Property C002 - 103 Kisco Avenue										
C002-AA001-01	2430436	0.2	+/- 0.2	8/4/2015	9:40	8/7/2015	10:16	Field Sample	Ground	Office Trailer, 2' East, 3' North from SW corner on top of a file cabinet
C002-AA002-01	2430444	0.2	+/- 0.2	8/4/2015	9:44	8/7/2015	10:18	Field Sample	Ground	Office Trailer, 6.2' West, 2.5' North from SE corner on PEI stand
C002-AA002-02	2430432	0.1	+/- 0.2	8/4/2015	9:45	8/7/2015	10:18	Field Duplicate	Ground	Office Trailer, 6.8' West, 2.5' North from SE corner on PEI stand
C002-AA003-01	2430423	0.2	+/- 0.2	8/4/2015	9:50	8/7/2015	10:20	Field Sample	Ground	Office Trailer, 2.3' West, 10' North from SE corner on top of a refrigerator
C002-AA004-01	2430411	0.3	+/- 0.2	8/4/2015	10:10	8/7/2015	10:23	Field Sample	Ground	Storage Trailer, 8' South from NW corner on a shelf
C002-AA005-01	2431993	0.2	+/- 0.2	8/4/2015	10:13	8/7/2015	10:24	Field Sample	Ground	Storage Trailer, 33' South from NW corner on a table
Property C003 - 105 Kisco Avenue										
C003-AA001-01	2389955	4.6	+/- 0.2	8/3/2015	11:21	8/6/2015	13:35	Field Sample	Ground	Warehouse #2, 9' North from SE corner on steel shelf
C003-AA002-01	2389951	2.7	+/- 0.2	8/3/2015	11:25	8/6/2015	13:37	Field Sample	Ground	Warehouse #2, 38' South from NW corner on wood shelf
C003-AA003-01	2390000	2.6	+/- 0.2	8/3/2015	11:26	8/6/2015	13:39	Field Sample	Mezzanine	Warehouse #2, 8.7' West from NE corner on wood shelf
C003-AA004-01	2389967	0.7	+/- 0.2	8/3/2015	11:46	8/6/2015	13:42	Field Sample	Ground	Warehouse #1, Bay-1, 20.6' North, 3.8' West from SE corner on PEI stand
C003-AA005-01	2389963	0.6	+/- 0.2	8/3/2015	11:50	8/6/2015	13:45	Field Sample	Ground	Warehouse #1, Bay-2, 5.4' West from NW corner on metal shelf
C003-AA006-01	2430420	1.7	+/- 0.2	8/3/2015	11:56	8/6/2015	13:47	Field Sample	Ground	Warehouse #1, Bay-3, 16.9' North from SE corner on PEI stand
C003-AA006-02	2422844	1.7	+/- 0.2	8/3/2015	12:02	8/6/2015	13:47	Field Duplicate	Ground	Warehouse #1, Bay-3, 17.4' North from SE corner on PEI stand
C003-AA007-01	2389974	5.2	+/- 0.3	8/3/2015	12:05	8/6/2015	13:40	Field Sample	Ground	Warehouse #2, 3.5' North from SE corner on a metal step ladder
C003-AA008-01	2390002	6.1	+/- 0.3	8/3/2015	13:16	8/6/2015	13:51	Field Sample	Ground	Main building, Showroom #1, 16.6' West from NE corner on top of a shelf
C003-AA009-01	2430414	6.6	+/- 0.3	8/3/2015	13:20	8/6/2015	13:53	Field Sample	Ground	Main building, Showroom #1, 3.3' North from SE corner on PEI stand

**Table 3**  
**Radon Analytical Results Summary**  
**Canadian Radium And Uranium Site**  
**Kisco Avenue, Mount Kisco, New York**

RST 3 Sample No.	Canister Serial No.	Results	Std. Error	Start		Stop		Sample Type	Floor	Location
		(pCi/L)	(pCi/L)	Date	Time	Date	Time			
Property C003 - 105 Kisco Avenue (Concluded)										
C003-AA010-01	2430406	6.4	+/- 0.3	8/3/2015	13:27	8/6/2015	13:55	Field Sample	Ground	Main building, Showroom #2, Middle of the room on a PEI stand
C003-AA011-01	2432038	7.0	+/- 0.4	8/3/2015	13:30	8/6/2015	13:58	Field Sample	Ground	Main building, Showroom #2, 9.3' West from NE corner on a stone water fall
C003-AA012-01	2431995	6.9	+/- 0.3	8/3/2015	13:36	8/6/2015	14:00	Field Sample	Ground	Main building, Showroom #3, 10.8' West, 9.4' South from NE corner on PEI stand
C003-AA013-01	2430445	9.3	+/- 0.4	8/3/2015	13:41	8/6/2015	14:04	Field Sample	Ground	Main building, Showroom #3, 18.3' North, 4.4' West from SE corner of a shelf
C003-AA014-01	2430405	3.7	+/- 0.2	8/3/2015	14:03	8/6/2015	14:08	Field Sample	Ground	Main building, Office #2, 1' North, 4' West from SE corner on a shelf
C003-AA015-01	2430421	3.7	+/- 0.3	8/3/2015	14:06	8/6/2015	14:09	Field Sample	Ground	Main building, Office #3, 5' North, 1.7' East from SW corner on a file cabinet
C003-AA016-01	2430477	7.0	+/- 0.3	8/3/2015	14:17	8/6/2015	14:31	Field Sample	Ground	Main building, Showroom #3, 45'North, 6' East from SW corner on PEI stand
C003-AA016-02	2430090	7.0	+/- 0.3	8/3/2015	14:18	8/6/2015	14:31	Field Duplicate	Ground	Main building, Showroom #3, 45.4'North, 6' East from SW corner on PEI stand
C003-AA017-01	2430435	3.2	+/- 0.2	8/3/2015	14:23	8/6/2015	14:36	Field Sample	Ground	Main building, Office #1, 5.8' West, 1' South from NE corner on a shelf
C003-AA018-01	2430426	6.4	+/- 0.3	8/3/2015	14:37	8/6/2015	14:48	Field Sample	Ground	Main building, Receiving area, 11.7' North, 3' West from SE corner on wood shelf
C003-AA019-01	2430453	7.0	+/- 0.3	8/3/2015	14:44	8/6/2015	14:50	Field Sample	Ground	Main building, Receiving area, 5.3' East, 3.7' South from NW corner on steel shelf
C003-AA020-01	2430416	13.6	+/- 0.4	8/3/2015	15:07	8/6/2015	15:33	Field Sample	Second	Main building, Showroom #4, 13.2' West, 11.8' South from NE corner on PEI stand
C003-AA021-01	2430429	15.6	+/- 0.4	8/3/2015	15:13	8/6/2015	15:34	Field Sample	Second	Main building, Conference room, On top of the class table
C003-AA022-01	2430463	15.9	+/- 0.4	8/3/2015	15:18	8/6/2015	15:36	Field Sample	Second	Main building, Office #5, On top of a countertop middle of North side
C003-AA023-01	2430409	13.6	+/- 0.4	8/3/2015	15:22	8/6/2015	15:38	Field Sample	Second	Main building, Office #4, On top of wood base cabinet on NE corner
C003-AA024-01	2432019	19.5	+/- 0.5	8/3/2015	15:27	8/6/2015	15:39	Field Sample	Second	Main building, Lobby #4, 6' East, 1.8' North from SW corner on a metal file cabinet
C003-AA025-01	2430433	18.1	+/- 0.4	8/3/2015	15:33	8/6/2015	15:41	Field Sample	Second	Main building, Reception area, 3' North, 1.3' West from SE corner on countertop
C003-AA026-01	2430450	18.0	+/- 0.5	8/3/2015	15:37	8/6/2015	15:43	Field Sample	Second	Main building, Office #6, 6.2' West, 5.5' South from NE corner on a desk
C003-AA026-02	2430425	17.4	+/- 0.5	8/3/2015	15:38	8/6/2015	15:43	Field Duplicate	Second	Main building, Office #6, 6.6' West, 5.5' South from NE corner on a desk
C003-AA027-01	2430462	10.3	+/- 0.4	8/3/2015	15:45	8/6/2015	15:47	Field Sample	Second	Main building, Room #2, On top of a cabinet in the middle of the room
FB01080315	2430410	0.1	+/- 0.2	8/3/2015	13:57	8/6/2015	14:05	Field Sample	Ground	Main building, Showroom #3, 18.3' North, 3.8' West from SE corner of a shelf
FB02080315	2430448	0.1	+/- 0.9	8/3/2015	15:41	8/6/2015	15:44	Field Sample	Second	Main building, Office #6, 2.1' West, 0.9' South from NE corner on a shelf